# MDS-MX1

# SONY. SERVICE MANUAL

**US Model** 

# **SUPPLEMENT-1**

File this supplement with the service manual.

**Subject: 1. CORRECTION** 

2. CHANGE OF OVER WRITE HEAD

3. PARTS CHANGED

4. CHANGE OF MECHANISM DECK


(ECN-CD600402)

#### 1. CORRECTION

• Correct your service manual as shown below.



Page	INCORRECT	CORRECT
29	[BD BOARD] Location : E-10	[BD BOARD] Location : E-10
	M 9 CP III III III III III III III III III	MIOSE PROPERTY OF THE PROPERTY



### 2. CHANGE OF OVER WRITE HEAD

The over write head has changed.

According to this change, the service form will be changed, so refer to How to discriminate (Over write head).

#### How to discriminate (Over write head)

		FORMER TYPE	<u></u>			NEW TYPE	
	ня90	153			HR9	2001	
Ref No.	Part No.	Description	Remark	Ref No.	Part No.	Description	Remark
153 HR901	1-654-446-11 1-500-175-11	OWH FLEXIBLE BOARD HEAD, OVER WRITE (RF322-74A)		HR901	1-500-304-21	not used HEAD, OVER WRITE	

The new part can be used instead of the former over write head.


	Ref No.	Part No.	Description	Remark	Ref No.	Part No.	Description	Remark
67		**	* EXPLODED VIEWS ***			<b>**</b> *	EXPLODED VIEWS ***	
	153 HR901	1-654-446-11 1-500-175-11	OWH FLEXIBLE BOARD HEAD, OVER WRITE (RF322-74A)		HR901	1-500-304-21	not used HEAD, OVER WRITE	

## 4. CHANGE OF MECHANISM DECK

The mechanism deck has been changed from MDM-2E to MDM-2ER.

Refer to How to discriminate (Mechanism deck) so that there is no interchangeability between MDM-2E and MDM-2ER.

#### How to discriminate (Mechanism deck)



### **MECHANISM SECTION (MDM-2ER)**

